

SB 223 – 05/07**Date of issue:**

31 May 2007

Affected aircraft:

TCDS No.: 679
Model: SIAT 223 Flamingo
Versions: V, A1, K1
Serial nos.: all

Subject:

Reinspections and a modification to the wings

Cause / reason:

To maintain airworthiness, reinspections and a modification to the wings are to be carried out. These are defined on pages 20/3 (cover page), 20/4 and 20/5 of the maintenance manual, which are to be incorporated into the maintenance manual with Revision No. 4 (also see attachment to this SB).

However, depending on the condition established during these inspections and at the modification, shorter intervals or further intermediate inspections may be prescribed individually for each aircraft.

Measures and time limits:

The measures and time limits are defined on pages 20/3 (cover page), 20/4 and 20/5, which are to be newly incorporated into the maintenance manual with Revision 4.

When due, the inspections and the modification will be carried out in the maintenance shop at the Manching site of EADS. Your point of contact at EADS:

Ulrich Hagmann, Tel. 089-607 28789.

Email: Ulrich.Hagmann@eads.com**Note:**

This Service Bulletin relates to change no. AE-SIAT223-01/2006, which has been approved by the authorities.

EADS Deutschland GmbH
Military Air Systems
Design Organization EASA.21J.026


Ulrich Hagmann